

1. Has anyone proposed fluid applied options for restoration of the main hanger?
 - a. We believe fluid applied would be the best option, financially and practically due to the current coating.

2. Have the purlins/structural supports been examined by an engineer?
 - a. New metal will be significantly heavier, this could pose many issues regarding load-bearing capacity of the building structure.